



CHECKED

KWS

CONCRETE OVERLAY AT FLOOR DRAIN

BILL OF MATERIAL

SYMBOL	ITEM	UNIT	QUANTITY	
	Deck Slab Repair (Partial)	Sq.·Yd.	19.0	
	Deck Slab Repair (Full Depth - Type I)	Sq. Yd.	5:0	
	Deck Slab Repair (Full Depth - Type II)	Sq. Yd.	5:0	
	Cleaning & Painting Exposed Rebar (Special)	Sq. Ft.	5	
	Protective Shield	Sq. Yd.	811	
	Protective Coat	Sq. Yd.	1,651	
	Bridge Deck Grooving	Sq. Yd.	1,367	
	Bridge Deck Latex Concrete Overlay, 2 ¹ 4"	Sq, Yd.	1,407	
	Bridge Deck Hydro- Scarification, 2 ¹ / ₄ "	Sq. Yd.	1,407	

▲ For information only to assist the Contractor in bidding. See Special Provision for "Bridge Deck Latex Concrete Overlay".

Notes:

- Deck and approach slab repair areas are estimated based on infrared thermographic deck survey and visual inspection completed in June 2009. Actual repair areas and locations shall be determined by the Engineer and shown on As-Built plans.
- Protective Shield, required for deck slab and/or parapet repairs, shall be installed according to Article 501.03 of the Standard Specifications. For limits of Protective Shield see General Plan and Elevation sheet.
- Deck drains (downspouts, floor drains, and scuppers) shall be cleaned prior to placement of the Latex Concrete Overlay. Cost of cleaning the deck drains is included in Bridge Deck Hydro-Scarification, 2^l₄".
- Gaps caused by distress around floor drains shall be filled with epoxy as specified in the Special Provision "Epoxy Injection". Cost included with Bridge Deck Latex Concrete Overlay, 2¹/₄".
- See Approach Slab Details sheets for Approach Slab removal and replacement details and quantities. See the Special Provisions for "Approach Slab Removal" and "Concrete Barrier Removal".
- 6. The Contractor shall exercise extreme care with the existing conduits in sections of the parapet to be removed and shall protect and support the conduit. The Contractor will be required to repair any damage done to the conduit to the satisfaction of the Engineer. No splicing will be allowed to any cable damage resulting from this work, instead the Contractor will be required to repair the entire span of any damaged cable at no additional cost to the Department.

BRIDGE DECK AND APPROACH SLAB REPAIRS STRUCTURE NO. 022-0112

SHEET NO. 5	F.A.I. RTE.	SECTION			COUNTY	TOTAL SHEETS	SHEET NO.
	290 355	22(1, 1-1,	2&3)RS-	7	DUPAGE	546	478
28 SHEETS					CONTRACT	NO. 60	G51
	FED. RO	AD DIST. NO.	ILLINOIS	FED.	AID PROJECT		

benesch Scompany SHE

spineers - Surveyors - Planners
205 North Michigan Avenue, Suble 2400
Chicago, Milmois 63801
312-565-0480
Job No. 10050
26